Wո	rk	O	der	m	51	444
7 T U	1 1	v	uu	11/	- J.	777

C

August 24, 2009 2:42:25 PM



Page 1

Item ID:

D3117-1-0980

Accept



Setup Start



Revision ID: Item Name:

Start Date:

Required Date: 08/31/09

08/24/09

Start Oty: 10.00 Req'd Qty: 10.00

Cust Item ID: Customer:

Reference:

Return 2009/ RA109065/R09-065

Approvals:

Process Plan:

Date: 09-08-34

Date:____

Tooling:

SPC (Y/N):

Run Hours

Date: Date:

Start Stop

Stop



Sequence ID/ Work Center ID

Operation Description

Revision Nbr

Set Up/

Draw Number Draw Rev.

Plan

Code

Accept Qty

Run

Qty

Reject Reject Number

1.9/1/25 (10)

Insp. Stamp

Draw Nbr

Rev C

QC:

D3117

100

QC5- Inspect part completeness to step on W/O

0.00



Quality Control

Memo

0.00

Parts are acceptable per drawing. Qty 10 of original B47475

120

Pick Kit

0.00

Packaging Packaging

0.00

130

Packaging

Packaging

Identify as per dwg & Stock Location: 57 407 0.00

Memo

Memo

0.00

Return to stock with the new batch #.

Make an inventory adjustment (see M.F or L.L)

(2/4/25 12

Work Order ID 51444

C

August 24, 2009 2:42:25 PM

Required Date: 08/31/09



Page 2

Item ID:

D3117-1-0980

Accept



Setup Start

Stop



Revision ID:

Item Name: **Start Date:**

08/24/09

Start Qty: 10.00

Req'd Qty: 10.00

Cust Item ID:

Customer:

Draw

Number

Reference:

Return 2009/ RA109065/R09-065

Operation

Description

Approvals:

QC:

Process Plan: Date:

QC21- Final Inspection - Work Order Release

Date: _____ SPC (Y/N):

Date:

Draw

Rev.

Plan

Code

Date:

Run

Reject

Qty



Sequence ID/

Work Center ID

140

Quality Control

Memo

Accept

Qty

Start

Stop



Insp.

Stamp

0.00

0.00

Tooling:

Set Up/

Run Hours

Reject

Number

09608/26 H